DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-014082 Address: 333 Burma Road **Date Inspected:** 07-Mar-2010

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: ZPMC and ABF **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** Tower

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector Mr. Wai Pau, was present during the times noted above for observations relative to the work being performed.

Caltrans QA inspector observed fifteen ZPMC workers in process of temporary bolting and holes drilling to the struts and 90 degree angle plates which connected to tower skin plate A, B, C, D and E. The struts located at elevation 23m thru 43m of north, south, east and west tower lift #1. The ZPMC will install only 25% bolts on each strut. The elevation 23m thru 43m have not been completed 25% temporary bolting. It'll be schedule continue tomorrow. Based on Caltrans QAI observations, no discrepancies were noted.

Caltrans QA inspector observed twenty ZPMC workers in process of temporary bolting to the interior skin connection plates which connected to skin plate A, B, C, D and E of north, south, east and west tower lift #1 and lift #2. The ZPMC will install only 50% bolts on each skin connection plate. The temporary bolting of interior skin connection plates have not been completed will be schedule continue tomorrow.

East tower lift #1 bearing stiffeners: - Caltrans QA Inspector observed two ZPMC welders in process FCAW process on 2nd stage exterior bearing stiffeners for skin A and D of east tower lift #1. The welds ID are ESD1-SA237 D/F-9/16. The material used for the 2nd stage exterior bearing stiffeners was reported by ZPMC QC as ASTM a 709M-345 plate with 60mm wall thickness. The weld is designed PJP weld use ZPMC joint detail WT10 with welded in 3G position. The bearing stiffeners weld joint has been pre heat prior welding. The FCAW was monitored and recorded by ZPMC and ABF QC inspector. Based on Caltrans QAI observations, no discrepancies were noted.

South tower lift #1 bearing stiffeners: - Caltrans QA Inspector observed six ZPMC welders in process FCAW process on 2nd stage exterior bearing stiffeners for skin C of south tower lift #1. The welds ID are SSD1-SA17-F/G-78/68/56/42//38/10. The material used for the 2nd stage exterior bearing stiffeners was reported by ZPMC QC

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

as ASTM a 709M-345 plate with 60mm wall thickness. The weld is designed PJP weld use ZPMC joint detail WT10 with welded in 3G position. The bearing stiffeners weld joint has been pre heat prior welding. The FCAW was monitored and recorded by ZPMC and ABF QC inspector. Based on Caltrans QAI observations, no discrepancies were noted.

CLOSING STATEMENT

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

As notes within report above.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Skyler Guest 15000422360, who represents the Office of Structural Materials for your project.

Inspected By:	Pau,Wai	Quality Assurance Inspector
Reviewed By:	Clifford,William	QA Reviewer